

VERNAL DISTRICT 2005 RECOATS UTAH/COLORADO

Site #	Line #	Mile Post	Legal Description	Work space needs	Task	Reference
AS-04-02	1400	251.8941 13299+80 13300+20	SEC 13 T-3-S R-102-W RIO BLANCO COLORADO N 39.69691 W 108.79529	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40' AND INSTALL MAG ANODES	BOTH LINES READ LOW
AS-04-03	1400	256.4402 13539+82 13540+22	SEC 25 T-3-S R-102-W RIO BLANCO COLORADO N 39.76041 W 108.78612	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40'	NORTH ROPE CANYON
AS-04-04	1400	261.3138 13796+06 13797+96	SEC 5 T-3-S R-101-W RIO BLANCO COLORADO N 39.8235 W 108.75164	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40' AND INSTALL MAG ANODE	BOTH LINES READ LOW EXCEL RETIRE SECOND TEST POST
AS-04-05	1400	262.1117	SEC 33 T-2-S R-101-W RIO BLANCO COLORADO	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40"	DRAGON TRAIL M/S
AS-04-06	1400	262.1354	SEC 33 T-2-S R-101-W RIO BLANCO COLORADO	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40'	BOTH LINES READ LOW ELPASO
AS-04-08 <i>Private</i>	3400	9.3009 490+83 491+33	SEC 26 T-1-N R-97-W RIO BLANCO COLORADO N 40.01939 W 108.25034	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50' AND INSTALL MAG ANODE	BOTH LINES READ LOW WGP -1.103

Site #	Line #	Mile Post	Legal Description	Work space needs	Task	Reference
AS-04-09	3400	27.2197 1436+95 1437+45	SEC 2 T-2-N R-99-W RIO BLANCO COLORADO N 40.17843 W 108.47382	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50' AND REPLACE TEST POST	
AS-04-10 <i>Private Utah</i>	1400 2406	0.0023	SEC16 T-6-S R-24-E UNITAH UTAH N 40.30709 W 109.21579	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 150'	RED WASH TAP AND 3 FOREIGN LINES AND 26"
AS-04-11 <i>Private Utah</i>	3406	0.1614	SEC 16 T-6-S R-24-E UNITAH UTAH	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	PIG LAUNCHER
AS-04-13	3422	0.8406	SEC 32 T-2-S R-101-W RIO BLANCO COLORADO	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	BOTH LINES READ LOW
AS-04-14	3422	3.5874	SEC 35 T-2-S R-102-W RIO BLANCO COLORADO	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	@ END OF DRAGON TRIAL LINE
AS-04-46 <i>Private</i>	1400	318.0278	SEC 9 T-5-S R-23-E UNITAH, UTAH N 40.40568 W 109.33081	100' X100' TEMPORARY WORK SPACE	RECOAT VALVE	4-2 E&W VALVES PRIVATE LAND No asbestos on half and unknown on half

Site #	Line #	Mile Post	Legal Description	Work space needs	Task	Reference
AS-04-47 Grand Jct	1400	234.8790 12401+41 12401+81	SEC 4 T-5-S R-102-W GARFIELD COLORADO N 39.47667 W 108.76490	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40'	HWY 139 -1.039 4/5/2005
AS-04-48 Grand Jct	1400	235.2996 12423+61 12424+01	SEC 3 T-7-S R-102-W GARFIELD COLORADO N 39.48121 W 108.75979	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40'	-.917 4/5/2005
AS-04-49 Grand Jct	1400	236.5856 12491+51 12491+91	SEC 34 T-6-S R-102-W GARFIELD COLORADO N 39.49682 W 108.75063	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40' AND INSTALL A MAG ANODE	@ A BOND WGP -.992 CANYON -1.080 SHUNT .01 +2.62 4/5/2005
AS-04-50 Grand Jct	1400	236.6614 12495+52 12495+92	SEC 34 T-6-S R-102-W GARFIELD COLORADO N 39.49779 W 108.75095	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40' AND INSTALL A MAG ANODE	WGP -1.015 EXCEL -.982 NO BOND 4/5/2005
AS-04-51	1400	250.3803 13219+87 13220+27	SEC 25 T-4-S R-102-W GARFIELD COLORADO N 39.67583 W 108.79010	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40'	-1.155 4/5/2005
AS-04-52	3400	37.2409 NEW MP 37.1914 1963+71 1964+21	SEC 7 T-2-N R-100-W RIO BLANCO COLORAD N 40.15744 W 108.65487	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	

Site #	Line #	Mile Post	Legal Description	Work space needs	Task	Reference
AS-04-53	3400	37.4441 1976+79 1977+29	SEC 7 T-2-N R-100-W RIO BLANCO COLORADO N 40.15715 W 108.65898	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	
AS-04-54	3400	37.5042 1979+97 1980+47	SEC 7 T-2-N R-100-W RIO BLANCO COLORADO N 40.15709 W 108.66045	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	
AS-04-55	3400	39.3797 2530+85 2531+35	SEC 18 T-2-N R-101-W RIO BLANCO COLORADO 40.14471 W 108.68927	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	SUDDEN DEATH TAP WGP -0.913 4/5/2005
AS-04-56	3400	47.9375	SEC 18 T-1-N R-101-W RIO BLANCO COLORADO N 40.05243 W 108.77316	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	
CIS-03-57	3400	32.9905 1741+90 1742+40	SEC 2 T-2-N R-100-W RIO BLANCO COLORADO N 40.16990 W 108.57841	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	
CIS-03-58	3400	35.3390 1865+90 1867+40	SEC 9 T-2-S R-100-W RIO BLANCO COLORADO N 40.16088 W 108.62054	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 150'	ALSO CIS—03-10 TEST POINT INSTALLED 2003

Site #	Line #	Mile Post	Legal Description	Work space needs	Task	Reference
CIS-03-59	3400	35.7178 1885+90 1892+40	SEC 9 T-2-N R-100-W RIO BLANCO COLORADO N 40.15944 W 108.63027	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 650'	
CIS-03-60	3400	35.9356 1897+39 1905+39	SEC 8 T-2-N R-100-W RIO BLANCO COLORADO N 40.15925 W 108.63127	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 800'	
CIS-03-61	3400	36.1249 1907+39 1910+39	SEC 8 T-2-N R-100-W RIO BLANCO COLORADO N 40.15828 W 108.63449	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 300'	
CIS-03-62	3400	36.3712 1918+96 1921+96	SEC 8 T-2-N R-100-W RIO BLANCO COLORADO N 40.15779 W 108.63892	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 300'	
CIS-03-63	3400	36.6647 1935+90 1939+90	SCE 8 T-2-N R-100-W RIO BLANCO COLORADO N 40.15766 W 108.64448	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 400'	THIS IS ALSO CIS-03012
CIS-03-64	3400	37.4886 1979+40 1980+40	SEC 7 T-2-N R-100-W RIO BLANCO COLORADO N 40.15705 W 108.65969	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	100'	

Site #	Line #	Mile Post	Legal Description	Work space needs	Task	Reference
CIS-03-65	3400	38.6155 2039+89 2040+39	SEC 12 T-2-N R-100-W RIO BLANCO COLORADO N 40.15285 W 108.67915	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 150'	
CIS-03-66	3400	36.5842 1931+65 1932+90	SEC 8 T-2-N R-100-W RIO BLANCO COLORADO N 40.15764 W 108.64357	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 125'	
CIS-03-67	1400	286.0486 15103+36 15104+61	SEC 36 T-2-N R-102-W RIO BLANCO COLORADO N 40.10590 W 108.89564	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 125'	
Private CIS-03-68	1400	286.8467 15145+50 15147+00	SEC 25 T-2-N R-103-W RIO BLANCO COLORADO N 40.11206 W 108.90745	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 150'	
CIS-03-69	1400	287.1060 15159+19 15161+44	SEC 25 T-2-N R-103-W RIO BLANCO COLORADO N 40.11442 W 108.91200	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 225'	
CIS-03-70	1400	289.3867 NEW MP 289.4340 15279+61 15282+11	SEC 22 T-2-N R-103-W RIO BLANCO COLORADO N 40.13328 W 108.94711	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 250'	Unknown on half and asbestos on half

Site #	Line #	Mile Post	Legal Description	Work space needs	Task	Reference
CIS-03-71	3400	36.8274 1944+49 1945+19	SEC 8 T-2-N R-100-W RIO BLANCO COLORADO N 40.15763 W 108.64744	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 70'	
CIS-02-39	1400	264.8900 13986+19 13989+19	SEC 16 T-2-S R-101-W RIO BLANCO COLORADO N 39.86958 W 108.73152	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 300'	
CIS-02-40	1400	265.3900 14012+59 14015+59	SEC 16 T-2-S R-101-W RIO BLANCO COLORADO N 39.87703 W 108.73223	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 300'	
CIS-02-41 <i>Private</i>	3400	40.7030 2148+91 2149+31	SEC 22 T-2-N R-116-W RIO BLANCO COLORADO N 40.13390 W 108.70730	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40'	
CIS-02-42	3400	40.7295 2150+21 2150+81	SEC 22 T-2-N R-101-W RIO BLANCO COLORADO N 40.13359 W 108.70768	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 60'	
CIS-02-43	3400	44.0818 NEW MP 44.1189 2329+48 2329+98	SEC 33 T-2-N R-101-W RIO BLANCO COLORADO N 40.09253 W 108.73064	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	

Site #	Line #	Mile Post	Legal Description	Work space needs	Task	Reference
CIS-02-44	3400	44.1386 NEW MP 44.1378 2330+48 2330+88	SEC 33 T-2-N R-101-W RIO BLANCO COLORADO N 40.09237 W 108.73090	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 40'	
CIS-02-45	3400	44.3214 2340+17 2340+82	SEC 4 T-1-N R-101-W RIO BLANCO COLORADO N 40.09073 W 108.73369	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 65'	
CIS-02-46	3400	44.3592 2342+17 2342+82	SEC 4 T-1-N R-101-W RIO BLANCO COLORADO N 40.09045 W 108.73434	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 65'	
CIS-02-47 <i>Private</i>	3400	44.5401 2351.72 2352+22	SEC 4 T-1-N R-101-W RIO BLANCE COLORADO N 40.08883 W 108.73719	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	
CIS-02-48	3400	45.5117 2403+02 2404+12	SEC 5 T-1-N R-101-W RIO BLANCO COLORADO N 40.07973 W 108.75150	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 110'	
CIS-02-49	3400	45.8202 2419+31 2420+21	SEC 8 T-1-N R-101-W RIO BLANCO COLORADO N 40.07674 W 108.75596	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 90'	

Site #	Line #	Mile Post	Legal Description	Work space needs	Task	Reference
CIS-02-50	3400	45.9225 2424+71 2427+01	SEC 8 T-1-N R-101-W RIO BLANCO COLORADO N 40.07570 W 108.75743	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 230'	
CIS-02-51	1400	266.3238 14061+89 14062+39	SEC 9 T-2-S R-101-W RIO BLANCO COLORADO N 39.89085 W 108.73581	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	
CIS-02-52	1400	266.1732 14053+94 14054+44	SEC 9 T-2-S R-101-W RIO BLANCO COLORADO N 39.88850 W 108.73447	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 50'	
AS-04-58	1400	273.1661 NEW MP 273.3430 14432+26 14432+96	SEC 7 T-2-S R-101-W RIO BLANCO COLORADO N 39.98268 W 108.77835	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 70'	NO NAME TRUCK TRAIL
CIS-03-72	3400	37.4015 1974+80 1976+70	SEC 7 T-2-S R-101-W RIO BLANCO COLORADO N 40.15720 W 108.65805	25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 190'	NEW MAY HAVE TO CARRY OVER UNLESS WE CAN ADD IT TO THE LIST SEGMENT 2
CIS-03-73	3400	35.0265 1849+40		25' EXTRA WORK SPACE ON BOTH SIDES OF THE EXISTING 50'	RECOAT 490'	LOOK AT FOR 2006 AFTER NEW 1688 CPS SITE HAS BEEN ON FOR AWHILE